

Preventative Maintenance Kits & Spare Parts



972 Centerville Road,
Pulaski, New York 13142
(315) 298-5121

VANTAGE HYDRONIC CONDENSING BOILERS (NATURAL GAS)

VANTAGE™



A consistent preventative maintenance routine is an important part of continuing efficient and reliable operation of your hydronic boiler system. This bulletin details the recommended parts to perform an annual PM of your Fulton boiler(s) along with suggested spare parts to have on hand if the need arises.

Preventative Maintenance of your Fulton boiler should be performed by a factory authorized Service Technician in accordance with the Installation, Operation and Maintenance Manual.

MAXON ANNUAL KIT VTG-2000 (POST 2011)	PART # 4-50-002100
Ignition Electrode	2-45-000524
Burner Discharge Gasket	2-45-000533
Burner Air Inlet Gasket	2-12-003028
Rectangular Blower Gasket	2-12-003029
Secondary Gasket	2-12-003021

MAXON ANNUAL KIT VTG-3000 (POST 2011)	PART # 4-50-003100
Ignition Electrode	2-45-000524
Burner Discharge Gasket	2-45-000532
Burner Air Inlet Gasket	2-12-003048
Blower Gasket	2-12-003035
Secondary Gasket	2-12-003031

MAXON ANNUAL KIT VTG-4000 (POST 2011)	PART # 4-50-004100
Ignition Electrode	2-45-000524
Burner Discharge Gasket	2-45-000532
Burner Air Inlet Gasket	2-12-003048
Blower Gasket	2-12-003049
Secondary Gasket	2-12-003041

MAXON ANNUAL KIT VTG-5000 (POST 2011)	PART # 4-50-005100
Ignition Electrode	2-45-000524
Burner Discharge Gasket	2-45-000532
Burner Air Inlet Gasket	2-12-003048
Blower Gasket	2-12-003045
Secondary Gasket	2-12-003041

VANTAGE™

ADDITIONAL SPARE PARTS FOR NATURAL GAS (MAXON) BURNERS	PART #
Condensing Heat Exchanger Gasket (Pre-2011)	2-12-000905
Round Burner Air Inlet Gasket (VTG-2000 – Pre-2011)	2-45-000530
Round Burner Air Inlet Gasket (VTG-3000 – Pre-2011)	2-45-000529
Blower Motor (VTG-2000 – Post 2011)	2-30-000772
Blower Motor (VTG-3000 – Post 2011)	2-40-000339
Blower Motor (VTG-4000 – Post 2011)	2-40-000622
Blower Motor (VTG-5000 – Post 2011)	2-40-003030
Ignition Wire Assembly (VTG-2000)	4-40-003020
Ignition Wire Assembly (VTG-3000)	4-40-003030
Ignition Wire Assembly (VTG-4000/5000)	4-40-003040
IR Scanner for use with LMV5	2-40-000465
UV Scanner for use with LMV3	2-40-000475
LMV37 Linkageless Combustion System	2-40-000471
Combustion Air Switch	2-30-000486
SQM 33 Servo Motor	2-40-000472
AZL Display for LMV3	2-40-000473
AZL Display for LMV5	2-40-000437
Low Water Cut Off (LWCO) Relay	2-40-000421
Type J Thermocouple	2-40-000801
UT32-A Temperature Controller	2-40-000863
RWF-55 Temperature Controller	2-40-000393
Operating Pressure Switch	2-40-000251
High Limit Pressure Switch	2-40-000294
1 ¹³ / ₁₆ " Socket for Primary Door Re-Torque	2-22-000571
1/2" x 3/4" Male Socket Adapter for Door Re-Torque	2-22-000570



972 Centerville Road
Pulaski, New York 13142
(315) 298-5121



Find your solution at:
www.fulton.com

FHS-VANTAGE-NG_PM-KIT-240521